



SUZUKI

2-Stroke

Service Bulletin

Subject: OIL TANK BREATHER OBSTRUCTION

Bulletin No: GENERAL-14

Date: May 1, 1975

Read and Initial

Manager _____

Parts _____

Service _____

There have been reported instances of engine damage, caused by oil starvation, due to a partial or total obstruction of the breather hole in the oil tank cap.

In each case it was found that the hole was covered by items such as: shop rags, rain gear, owner's manuals, etc, placed under the seat, and over the oil cap, by the individual owners.

Please caution your customers about this possibility since this is not a manufacturers defect and any necessary repairs would therefore not be covered under warranty.