TWO STROKE

# SUZUKI
## TWO STROKE
# Service Bulletin

Bulletin No: Tool Bulletin #10
Date: June 23, 1978

Read and Initial

Manager _____
Parts Mgr. _____
Service Mgr. _____
Mechanics _____ _____ _____

## SS-I, SS-II ELECTRO TESTER REPAIR

ESI, Electro-Specialties Inc., in Waukesha, Wisconsin has been appointed as a repair service for Suzuki Electro Testers. ESI is equipped to provide complete repairs in 5 working days on normal repair jobs.

A repair charge limit of $60.00 has been established as a guideline. If the necessary repairs will cost more than $60.00, ESI will mail a card to your dealership advising you of the new repair estimate. Extensively damaged units may also require additional repair time.

ESI is an independent organization so all transactions are to be made directly with them. U. S. Suzuki can not provide direct assistance concerning billing or shipping. Please ship your tester freight prepaid, directly to:

ESI
1345 Pearl Street
Waukesha, Wisconsin 53186
Phone (414) 544-1344

Please return all of the test leads with your tester. In many instances the problem is with the test leads rather than with the Electro Tester. This will help eleminate unnecesary repair charges.

NOTE: Mark your Electro Tester clearly with your dealership number and name!

Upon completion of the repairs ESI will ship the electro tester back to you by UPS, COD. The return shipping costs and repair costs are included in the COD charges.

Questions concerning this repair program should be directed to ESI.

U. S. SUZUKI
TECHNICAL SERVICE DEPARTMENT
U.S. Suzuki Motor Corp. • 13767 Freeway Drive • Santa Fe Springs, California 90670 • (213) 921-4461