


# KH500-A8 Wiring Diagram (US Model)



- Right Front Turn Signal Light 12V 23W
- Speedometer Light 12V 3.4W
- Turn Signal Indicator Light 12V 3.4W
- High Beam Indicator Light 12V 1.7W
- Neutral Indicator Light 12V 3.4W
- Brake Light Failure Indicator Light 12V 3.4W
- Tachometer Light 12V 3.4W
- Ignition Switch
- Headlight 12V 60/35W
- Left Front Turn Signal Light 12V 23W

Ignition Switch Connections

Lead	Ignition	E	H.L.	Tail	Battery	Coil
Color	Bk/W	Bk/Y	Blue	R/W	White	Brown
OFF	ON	ON	ON	ON	ON	ON
PARK						